

NE RLY

CE's Circular No. 71 of 1988.

Sub : Maintenance of Level Crossings.

It has been noticed that the maintenance of road surface of Level Crossings is not good, wherever maintenance has been given to the IOWs.

2. Henceforth the road surface of the Level Crossings, & particularly restoration of road surface after overhauling, will be the responsibility of PWIs and not of IOWs.

3. Necessary equipment, stores and funds may be placed at the disposal of PWIs to carry out the maintenance of road surface of Level Crossings.

(W/275/4/Pt.I/4A)

[Signature]
Chief Engineer
01/11/88

Distribution:

- DRM(Engg)/IZN, LJN, BSB, SEE, SPJ (with 4 copies each).
- CTE, CE/East, CE/West, Dy.CE/T-1.
- Spare copy for Case No. W/218/0/4A.