

NORTH EASTERN RAILWAY

CE'S P.WAY CIRCULAR NO.15 OF 1957.

CASE NO.W/537/O/Pt.T/W-4

OPENING OF NEW LINES IN STATION YARDS ETC.

Recently a passenger train was derailed while entering a newly opened track in a Station Yard. From enquiry it was revealed that the track in question was not tested as is usually done prior to taking the passenger train on the new line. It is, therefore, once more emphasized that whenever any new line is to be opened, it should always be tested by a light engine or a ballast train before allowing any passenger train on this. It will be the AEN's personal responsibility to see that this practice of testing new line is not neglected before issuing safety certificate for the new line. Please draw the attention of all the staff concerned.