

2017-18						
S.No	Date of accident,Ti me & Div.	Brief Particulars	At/betn. Stns.	Cause	Staff Responsible	Punishment
1	22.04.2017 17.00 hrs. BSB/BG	A Maruti Swift Dzire Car No. UP 65BD-1645 dashed with T/E of 12334 Express between Ahimanpur-Madhosingh on UMLC No.32/C at Km.254/2-3.	Ahimanpur-Madhosingh	Negligent driving by Maruti Swift Dzire Car driver.	No Rly. staff held responsible.	No Rly. staff held responsible.
2	02.09.2017 18.10 hrs. BSB/BG	DN BUI-GCT derailed by four wagons while leaving Hardatpur station yard.	Hardatpur	Track defect- Poorly maintained turn in and turn out curve.	P- Sri Roopam Vikas, SSE/P.Way/Con/BSB	Reduction to a lower grade for a period of 3 yrs. with loss of seniority.
3	18.09.17, 19.20 hrs. LJN/BG	2 leading wheels of front trolley of Locomotive No.12203 of Train No.54322 Up derailed between Sitapur Cantt.-Sitapur City on Point No.K-1 of Thompsonganj siding.	Burhwal-Sitapur	1. Rough griding of switch rail of Point No. K-1. 2. Improper curvature Point No. K-1	P- Sri Chhotey Lal, SSE/P.Way/STP	One grade below from GP 4800/-(L/8) of 66000/-& fixed to GP 4600/-(L/7) of Rs.64100/-for a period of three years from the date of this order with cumulative effect on pension & seniority.
					S- Sri Sunil Singh, ADEN/Line/LJN	Holding of three month increment temporarily.
4	19.09.17, 07.11 hrs. LJN/BG	2 leading wheels of front trolley of middle Locomotive of Goods Train No. UP Longhaul derailed near Point No. K-1 of Thompsonganj siding.	Burhwal-Sitapur	1. Rough griding of switch rail of Point No. K-1. 2. Improper curvature Point No. K-1	P- Sri Chhotey Lal, SSE/P.Way/STP	One grade below from GP 4800/-(L/8) of 66000/-& fixed to GP 4600/-(L/7) of Rs.64100/-for a period of three years from the date of this order with cumulative effect on pension & seniority.
					S- Sri Sunil Singh, ADEN/Line/LJN	Holding of three month increment temporarily.
5	27.01.18, 21.10 hrs. BSB/BG	DN Sarai Goods Train loaded with wheat while entering in Kusumhi station yard line No.4, derailed by 4 wagons. DN Main Line was blocked.	Bhatni-Gorakhpur Cantt,	Chipped off switch & defect in rolling stock.	P- Sri Ramesh Mishra, SSE/P.Way.CC	Reduction of pay in lower grade for a period of 3 yrs. with loss of seniority.
					P- Sri Pratap Nagar, Workshop/W.Rly.	Imposed(Employee Retired)
					S- Sri Sanjay Kumar, SSE/P.Way/BTT	With holding of increment for the period of one year.
2018-19						
Sl. No.	Date of accident,Ti me & Div.	Brief Particulars	At/betn. Stns.	Cause	Staff Responsible	Punishment
1	06.04.18 21.27 hrs. BG/BSB	Train No.55183 dashed with Road-cum-Rail vehicle (Mobile Flash Butt Welding Machine) at UMLC No.3 KM.47/6 and after dashing its T/E No.40307 derailed by 4 wheels between Rajapatti-Mashrakh stations.	Rajapatti-Mashrakh	Negligent driving by Rail-cum-Road Vehicle driver	P- M/s ITC Ltd., 84/22, Fazalganj, Kanpur.	Penalty impose 1 Lakh deduct from bill

2	26.04.18 06.45 hrs. BG/BSB	School Van dashed with T/E No. 16258 WDM-3A of Pass. Train No. 55075 at UMLC No.45/C KM. 75/0-1 between Tamkuhi Road-Dudahi stations.	Tamkuhi Road-Dudahi	Negligent driving by Maximo School Van Driver.	No Rly. staff held responsible.	No Rly. staff held responsible.
3	11.10.18 12.59 hrs. BG/LJN	Rear bogie of front SLR of Train No.13020 DN derailed by 2 wheels after passing first facing point no.202 of Domingarh station.	Gorakhpur-Basti	Due to hitting of 90 meter long rail panel with the wheels.	P- SSE/P.Way/Chureb	WIT 35 month
					P- JE/P.Way/Sahjanwa	WIT 03 years
					P- SSE/P.Way/Khalilabad	WIT 03 years
4	11.12.18 09.29 hrs. BG/LJN	Train No.12530 derailed by 02 rear wheels of front trolley of 4th coach (NC 13486/GS) from T/E while entering in Line No.3 of Basti station.	Basti station	Cattle run over.	S-LP/GKP	WIT- 24 months
					S-Sr.ALP/GKP	WIT-24 months
					S-Guard/LJN	WIT-12 months
5	31.03.19 09.40 hrs. BG/BSB	Derailment of Train No.19046 Up (Tapti Ganga Express) by 13 coaches from rear while passing home signal of Gautam Asthan station.	Chhapra-Aunrihar	Due to shifting of track	P- JE/P.way/Suremanpur	Reduction of a lower grade for period of 03 years with loss of seniority
					P-SSE/P.Way/BUI	Reduction of a lower grade for period of 03 years with loss of seniority
					Keyman Gang No.1/CA	Reduction of a lower grade for period of 03 years with loss of seniority

2019-20

NIL

2020-21

NIL

2021-22

Sl. No.	Date of accident, Time & Div.	Brief Particulars	At/betn.Stns.	Cause	Staff Responsible	Punishment
1	26.12.2021 23.35 hrs.BG/IZN	Fire in Coach no. 06493GS NE,third from TE of train 05389 KSJ-FBD passenger.	Samshabad-Farrukhabad	Fire has been intentionally/unintentionally caused by unknown persons/passengers.	P-Nil	
					S- Aman bharadwaj/Guard/KSJ	WIT-06 month
					Virender Kumar/IPF/FBD	WIT-06 month
					Narenra km Mishra	WIT-06 month
					Shashi kant Singh SM FBD	WIT-06 month
					Arvind kumar CTNL,IZN	WIT-06 month
					Ram Jeevan,CTNI-IZN	WIT-06 month
					Ram Naresh,SM/GWA	WIT-06 month

2022-23						
Sl. No.	Date of accident, Time & Div.	Brief Particulars	At/betn. Stns.	Cause	Staff Responsible	Punishment
1.	28.10.2022 10:40 hrs BG/IZN	Derailment of GSLRD/144735 NCR of passenger train no. 04134, next to train engine derailed by 2 wheels of front trolley	Kayam ganj-Khudaganj	Use of short closure i.e. 1.35 m rail piece which was less than prescribed length of 5.5/4 m rail piece. Use of pair of joggle fish plates instead of normal fish plates on either side of joints on the 1.35 m rail closure. Wrong measurement of rail piece prepared for insertion on the track	P-Shailender Kumar Singh/SSE/P Way/Gursahayga	Remove from service
2023-24						
NIL						
2024-25						
Sl. No.	Date of accident, Time & Div.	Brief Particulars	At/betn. Stns.	Cause	Staff Responsible	Punishment
1.	18/07/2024 14:37 BG/LJN	Derailment of Train No. 15904 CDG-DBRG Exp. in block section Motiganj- Jhilahi of Gonda-Basti section. 13 coaches are derailed & 06 coaches are capsized.	Motiganj - Jhilahi	Dynamic buckling due to abnormal LWS	P-Engineering department <ul style="list-style-type: none"> • Key man • JE • SSE S- <ul style="list-style-type: none"> • Sr. DEN/I/LJN • SM/MOTG • CTNL/LJN 	Under Process