



MLN COACHING DEPOT

**DEPOT
AT A
GLANCE**



COACHING DEPOT MLN**Sri. P.K.SINGH****CDO/ASH****Holding of Coaches**

ICF MG : 114
LHB:00
Total : 114

PRIMARY RAKES

Train No.		No. of Rakes	Days of run
05361/05356	ICF (MG)	5	D
05319/05320	ICF (MG)	1	6,7

Train Passing

Trains	Max.	Min.	Avg.
RBPC/Day (BG)	4	4	4
Ter/Org/ Day (MG)	6	5	5

STAFF POSITION

SN	CATEGORY	SAN	ON ROLL
1	Total C&W Supervisor	7	2
2	Total Group C Staff	47	39
3	Total Ministerial Staff	1	0
4	Total Group D staff	21	9
5	TOTAL	76	50

Coach Maintenance Facility

Pit no.	Length (LHB coach)	Length in mtrs.	High pressure Coach Washing	Sick Line Capacity
1	12 (ICF)	250	-	04 Coaches

Watering Facility(Hydrant)

PF No.	Hyd Length (No.of Coaches)	Washable Apron	Pathway/ Drain Cover	Rolling In Lights	Booster Pump	VHF Sets
1 - BG	26	Not Available	Not Available	Available	Not Available	Available
2 - BG	26	Not Available	Not Available	Available	Not Available	Available
3 - MG	12	Not Available	Not Available	Available	Not Available	Available
4 - MG		Not Available	Not Available	Available	Not Available	Available
5 - MG	12	Not Available	Not Available	Available	Not Available	Available

Disaster Management

ART (B CLASS MG) : 06 Coaches, ARME (SCALE 1 MG) : 02 Coaches, BG SPART (Proposed)

ART/MLN

Road Vehicle

The road vehicle is designed to transport the T&P and M&P items kept at MG ART at Malani from one place to another as per requirement at the accident site.

